## SHUTTLE CRITICAL ITEMS LIST - ORBITER

SUBSYSTEM : ORBITAL MANEUVER FMEA NO 03-3 -4501 -1 REV: 12/01/87

ASSEMBLY :ENGINE SUBSYSTEM CRIT. FUNC: 1
P/N RI :MC621-0009 CRIT. HDW: 1

F/H VENDOR: 1186829 VEHICLE 102 103 104
CUANTITY 12 EFFECTIVITY: X X X

QUANTITY :2 EFFECTIVITY: X X X X :ONE FOR EACH ENG SUBSYS PHASE(S): PL X LO X OO X DO X LS

REDUNDANCY SCREEN: λ-APPROVED BY (NASA): APPROVED BY: PREPARED BY: for SSM John Marson fen -144 V F ROZNOS DE5 DES REL Made # 212 64 12 -3-9.7 REL C M AKERS REL QE N J SMITH QΞ

ITEM:

à.

:

TANK, PRESSURANT, GN2, PNEUMATIC ACTUATION SUPPLY, TITANIUM (GALAV).

FUNCTION: STORES GASEOUS NITROGEN AT A MAXIMUM WORKING PRESSURE OF 3000 PSI AN PROVIDES PRESSURIZING GAS FOR THE ENGINE BIPROFELLANT VALVE ACTUATORS TANKS ARE LOCATED ON THE ENGINE SUB ASSEMBLY IN EACH POD.

FAILURE MODE: STRUCTURAL FAILURE, RUPTURE, EXTERNAL LEAKAGE.

CAUSE(S):

MATERIAL DEFICIENCY, WELD DEFECT, FAULTY FABRICATION, STRESS RISER
TEST DAMAGE, STRESS CORROSION, PROPELLANT LEAK, SHOCK, VIBRATION.

EFFECT(S) ON:
(A) SUBSISTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE

- (A) LOSS OF FUNCTION. LOSS OF ABILITY TO RESTART ENGINE.
- (B) LOSS OF INTERFACE SUBSYSTEM. POSSIBLE DAMAGE TO THE ONE HEA
- (C) POSSIBLE EARLY MISSION TERMINATION. REDLINE ADDITIONAL PROPELLANT FOR RCS BACKUP DEORBIT. MEXT PLS DEORBIT IF SUFFICIENT PROPELLANT NO AVAILABLE.
- (D) POSSIBLE POD DAMAGE AND CREW LOSS IF FAILURE PROPAGATES.

DISPOSITION & RATIONALE:
(A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY (E) OPERATIONAL USE

03-3 - 171

## SHUTTLE CRITICAL ITEMS LIST - ORBITER

BSYSTEM : ORBITAL MANEUVER

FMEA NO 03-1 -4501 -1

REV:12/01/87

#### ) DESIGN

THE FACTOR OF SAFETY (PROOF) IS 2.0 X WORKING PRESSURE AND THE FACTOR OF SAFETY (BURST) IS 4.0. DESIGN BURST IS 7200 PSIG, ACTUAL BURST WAS 13,500 PSI (TANK FLANGE FAILURE). TANKS ARE OF LOW CAPACITY (5.0 IN DIAMETER). COMPLETE STRESS AND FLAW GROWTH ANALYSIS FOR EACH TANK SEGMENT WAS PERFORMED. FRACTURE CONTROL REQUIREMENTS ARE IMPOSED. SHRAPNEL NOT PRODUCED IN RUPTURE FAILURE DUE TO LOW STRESS LEVELS.

#### i) TEST

QUALIFICATION TEST

THERMAL CYCLES (-23 TO +150 DEG F), ENDURANCE (1000 PRESSURIZATION CYCLES), VIBRATION TESTING AT ENGINE LEVEL. QUALIFIED AS FART OF ENGINE ASSEMBLY - 138 FIRINGS DURING ENGINE QUAL, 498 FIRINGS AT POD LEVEL AT WSTP.

#### ACCEPTANCE TEST

EXAMINATION OF PRODUCT, WELD EVALUATION FOR EVIDENCE OF STRESS RISER OR OTHER FLAWS, PROOF PRESSURE AND LEAK.

### GROUND TURNAROUND

V43CBO.210 PERFORMS FIRST FLIGHT LEAK TEST.

V41CBO.280 PERFORMS PRESSURE DECAY OF GNZ SYSTEM EACH FLIGHT.

V43CFO.030 PERFORMS PNEUMATIC SYSTEM GN2 SERVICING AND VERIFIES

CONFORMANCE TO SE-S-0073 EVERY FLIGHT.

GN2 TANK AND ACCUMULATOR PRESSURE MONITORED EACH FLIGHT FOR INDICATIONS OF LEAKAGE.

#### C) INSPECTION

RECEIVING INSPECTION

MATERIALS AND PROCESSES CERTIFICATIONS ARE VERIFIED BY INSPECTION.

CONTAMINATION CONTROL

CLEANLINESS TO LEVEL 200 AND CORROSION PROTECTION PROVISIONS ARE VERIFIED BY INSPECTION.

ASSEMBLY/INSTALLATION

MANUFACTURING, ASSEMBLY AND INSTALLATION PROCEDURES ARE VERIFIED BY INSPECTION. CRITICAL DIMENSIONS AND SURFACE FINISHES ARE VERIFIED BY INSPECTION.

CEITICAL PROCESSES

THE WELDING PROCESS AND VERIFICATION THAT WELDS MEET SPECIFICATION REQUIREMENTS ARE VERIFIED BY INSPECTION.

NONDESTRUCTIVE EVALUATION

PENETRANT AND RADIOGRAPHIC INSPECTION OF WELDS ARE VERIFIED BY INSPECTION. ULTRASONIC INSPECTION OF ANNEALED MIL-T-9047 BAR STOCK IS VERIFIED BY INSPECTION.

# SEUTTLE CRITICAL ITEMS LIST - ORBITER

SUBSYSTEM : ORBITAL MANEUVER

FMEA NO 03-3 -4501 -1 REV:12/01/67

TESTING

TEST EQUIPMENT AND TOOL CALIBRATION ARE VERIFIED BY INSPECTION. ACCEPTANCE TEST IS VERIFIED BY INSPECTION. PRESSURIZATION CYCLE HISTORY LOG IS VERIFIED BY INSPECTION. MICRO-ETCH OF HEMISPHERES FOR ALPHA SEGREGATION IS VERIFIED BY INSPECTION.

HANDLING/PACKAGING HANDLING, PACKAGING, STORAGE AND SHIPPING REQUIREMENTS ARE VERIFIED BY INSPECTION.....

- (D) FAILURE HISTORY NONE.
- (E) OPERATIONAL USE FOR EXTERNAL LEAKAGE AFFECTED ENGINE WILL NOT BE USED FOR ON-ORSIT BURNS. SAVE ACCUMULATOR PRESSURE FOR DEGRBIT BURN START. FOR LOSS OF ACCUMULATOR PRESSURE COMPLETE MISSION REQUIREMENTS USING CROSSFEED FOR PROPELLANT UTILIZATION. REDLINE ADDITIONAL PROPELLANT FOR RCS BACKUP DEORBIT. MEXT PLS DEORBIT IF SUFFICIENT PROPELLANT NOT AVAILABLE. POSSIBLE MISSION IMPACT. DECREASE IN PROPELLANT AVAILABLE FROM OMS TO

RCS FOR INTERCONNECT FOR ON-ORBIT OPERATION.